



Enabling Industrial IoT

SNYPER-LTE+ SNYPER-LTE+ Spectrum CASE CONTENTS

SNYPER-LTE+/SNYPER-LTE+ Spectrum Case Contents

- 1 SNYPER-LTE+ or SNYPER-LTE+ Spectrum
- 2 Multi-region PSU with 4 adapter heads
- 3 0.5M USB Cable
- 4 USB Car Charger
- 5 Omni-directional Antennas – General Purpose (Black) and 2600MHz (Silver/Grey)
- 6 liveSCAN Directional Antenna (Spectrum model only)
- 7 1.5M Extension Cable for Directional Antenna (Spectrum model only)



SNYPER LTE+ / SNYPER LTE+ Spectrum

QUICK START GUIDE



FIRST STEP BEFORE USE

1. BATTERY CHARGE: Charge the unit for 4-6 hours or until the red charge light is extinguished
2. SOFTWARE REVISION: Go to www.siretta.com/software-library to check for latest software
 - Click on the "(V3)" tab
 - Compare website revision to that in the SNYPER's "ABOUT" menu (this can be accessed from the "MAIN MENU")
 - Upgrade the software accordingly, following the procedure in the SNYPER-LTE+ family manual. For both the EU and USA versions: https://www.siretta.com/?smd_process_download=1&download_id=8601
3. SETTING TIME: Power up the SNYPER. From "MAIN MENU" select "Setup" > "Set Time". Use the keypad arrows to set date/time so you can timestamp your surveys. You are now ready to go.



POWER ON TO BRING UP MAIN MENU SELECTIONS

SURVEY



NEW SURVEY OPTIONS

- 1) Select Full, LTE, UMTS or GSM
- 2) Press to start survey
- 3) Leave device to complete survey



POST SURVEY OPTION 1

- 1) Select Show Results
 - 2) Press for liveSCAN (Spectrum only)
- Use key to exit



POST SURVEY OPTION 2

- 1) Select Show Summary
- Use key to exit



POST SURVEY OPTION 3

- 1) Select Save Results
- This is only necessary if Auto Save is off
- Use key to exit

SAVED RESULTS



STORED SURVEY

- 1) Select results file you wish to view
 - 2) Select Show Results, Show Summary, or Export Results
- Use key to exit



SETUP



- Language: ENG/DEU/FRA/ITA/SPA
Display: Screen brightness and text colours
Auto off: Auto switch off and dimming
Documents: Results file types and Auto Save
Sound: On/Off
System: Mode and region of operation
Set Time: Set date and time
Factory Reset: Return to default settings
- Use key to exit

ABOUT



- Key reference parameters about the device
- Use key to exit

PC CONNECT



- PC CONNECT
- 1) Connect USB cable between device and PC
 - 2) Select ON to enable USB connection, begin results download
 - 3) Copy files required to PC
 - 4) Select OFF to disable connection
- Use key to exit
- You can then view results files on your PC

For more detailed information,
please visit our website at www.siretta.com